

Carrying out zinc-rich coating operations

Overview

This standard identifies the competences you need to carry out material finishing operations by zinc-rich coating methods, in accordance with approved procedures. You will be expected to confirm with the authorised person, such as your immediate supervisor, that the equipment is ready for the coating operations to be performed and that all the required components/materials and consumables are available. You will be required to operate the zinc-rich coating equipment, in line with safe working practices and approved procedures, continuously monitoring the coating operations and where necessary, making minor adjustments or seeking help from the authorised person to make the required adjustments, in order to ensure that the work output is to the required quality. Meeting production targets will be an important issue and your production records must show consistent and satisfactory performance. Your responsibilities will require you to comply with organisational policy and procedures for the zinc-rich coating activities undertaken and to report any problems with these activities that you cannot personally resolve, or are outside your permitted authority, to the relevant people. You will be expected to work to instructions, with a minimum of supervision, taking personal responsibility for your actions and for the quality of the work that you carry out. Your underpinning knowledge will be sufficient to provide a sound basis for your work and will enable you to adopt an informed approach to applying zinc-rich coating procedures. You will have an understanding of the zinc-rich coating process and its application and will know about the equipment, materials and consumables in adequate depth to provide a sound background for carrying out the activities, recognising and reporting coating defects and ensuring the completed components are to the required specification. You will understand the safety precautions required when working with zinc-rich coating equipment and materials. You will be required to demonstrate safe working practices throughout. You will also understand your responsibilities for safety and the environment and the importance of taking the necessary safeguards to protect yourself and others in the workplace.

Carrying out zinc-rich coating operations

Performance criteria

You must be able to:

1. work safely at all times, complying with health and safety legislation, regulations, directives and other relevant guidelines 2. follow work instructions and specifications ensure the material surfaces to be treated are prepared for the finishing operations 3. check that the finishing equipment and treatment solutions are set up and maintained at satisfactory operating conditions and levels 4. carry out the treatment process following operating procedures and to meet the component specification requirements 5. ensure that the treated workpiece achieves the required characteristics and meets the finishing specification 6. deal promptly and effectively with problems within your control and report those that cannot be solved 7. ensure that work records are completed, stored securely and available to others, as per organisational requirements 8. leave the work area in a safe condition on completion of the activities, as per organisational and legal requirements

Knowledge and understanding

You need to know and understand:

1. the specific safety precautions to be taken whilst carrying out the activities (including any specific legislation, regulations or codes of practice relating to the activities, equipment or materials)
2. the health and safety requirements of the work area and the activities, and the responsibility these requirements place on you
3. the hazards associated with the activities, and how to minimise them and reduce risks
4. the personal protective equipment and clothing (PPE) to be worn during the activities
5. the importance of keeping the work area clean and tidy, including the use of 5S or similar techniques
6. how to obtain and interpret the production documentation required during the coating activity
7. the basic principles of the operation of zinc-rich coating equipment
8. how to prepare and make additions to processing media
9. the visual checks to be made on components prior to coating
10. the pre-treatments to be carried out on components prior to coating
11. the methods used to hold/secure components during the zinc-rich coating process
12. the importance of monitoring the equipment settings and coating media during the zinc-rich coating process
13. the types of adjustment that can be made to equipment settings to maintain component quality
14. how to identify zinc-rich coating process faults (such as missed coating, poor colour, jig damage, under-curing, parts sticking together)
15. the basic quality checks to be carried out on zinc-rich coated components
16. how to pack and store finished components to avoid damage
17. the importance of completing the production documentation throughout the zinc-rich coating process
18. the extent of your own responsibility and whom you should report to if you have problems that you cannot resolve
19. how to access, use and maintain information to comply with organisational requirements and legislation

Carrying out zinc-rich coating operations

Scope/range related to performance criteria

1. Apply zinc-rich coatings, carrying out all the following activities: 1. use the correct issue of process documentation (specifications, job cards, quality control documentation) 2. adhere to health and safety regulations, systems and procedures to realise a safe system of work 3. confirm with the authorised person that the plant is ready for carrying out the coating operations 4. maintain sufficient quantities of process materials and components during the production cycle 5. seek any necessary instructions or training the operation of the coating equipment 6. follow the defined operating procedures ensure that the equipment settings and coating media are adjusted (either by yourself or the authorised person) to maintain the correct customer specification 7. leave the work area in a safe and clean condition

2. Apply zinc-rich coatings, using one of the following techniques: 1. dip spin coating 2. flow coating 3. dip drain coating 4. spraying techniques

3. Carry out three of the following activities during the zinc-rich coating process: 1. segregate any defective components or batches (pre and post coating) 2. carry out pre-treatments (such as degreasing, cleaning, shot and air blasting) 3. jiggling 4. load components safely into plant 5. monitor the coating media and process settings (time, temperature, speed, viscosity, agitation) 6. safely make adjustments to the coating media or process settings 7. carry out post coating operations (curing using electrical, gas or induction methods)

4. Identify four of the following types of defect in zinc-rich coated components: 1. missed coating 2. poor colour 3. touch marking 4. jig damage 5. under-curing 6. components sticking together

5. Carry out four of the following checks on zinc-rich coated components: 1. free from damage 2. free from contamination 3. surface quality/appearance 4. completeness of coating 5. wet film thickness 6. thread tolerances 7. adhesion of coating 8. completion of the curing process

6. Carry out three of the following completion activities on : 1. check that components are cool before packing 2. place components in the specified container/area 3. store components in the correct quantities/weight 4. use the correct packaging to avoid damage 5. complete the production documentation 6. place all labels/production documentation in the specified location 7. clean the tools and equipment

7. Check components finished with zinc-rich coatings comply with one of the following quality standards: 1. military or aviation 2. current industry standards or codes of practice 3. international standards company standards and requirements 4. customer standards and procedures

Carrying out zinc-rich coating operations

Developed by	Enginuity
Version Number	2
Date Approved	30 Mar 2020
Indicative Review Date	31 Mar 2023
Validity	Current
Status	Original
Originating Organisation	Semta
Original URN	MPF2.44
Relevant Occupations	Engineering and Manufacturing Technologies, Manufacturing Technologies, Process Operatives, Process, Plant and Machine Operatives
Suite	Materials Processing and Finishing Suite 2
Keywords	Engineering; manufacturing; processing; casting; zinc rich; dip spin; flow; deep drain