
Overview

This unit is about your contribution to post-job operations.

This unit deals with the following:

- 1 Performing post-job worksite inspection
- 2 Preparing for worksite departure

During this work you must take account of the relevant operational requirements and safe working practices AS THEY APPLY TO YOU.

Previous Version:

Unit 4 National Occupational Standards in Measurement Processes – May 2003

COGMP4

Perform post-measurement processes operations

Performance criteria

You must be able to:

- P1 work safely in accordance with operational requirements
- P2 effectively check all relevant plant and process is left safe
- P3 effectively return the system to service as appropriate
- P4 complete all documentation relevant to the operation
- P5 fulfil all responsibilities regarding equipment and the spares
- P6 effectively complete all local works Permit to Work procedures
- P7 notify relevant personnel of completion
- P8 accurately perform all relevant calculations
- P9 accurately record and highlight potential mis-measurements
- P10 actively and effectively take part in a close-out meeting with relevant personnel

COGMP4

Perform post-measurement processes operations

Knowledge and understanding

You need to know and understand:

- K1 what the post-job inspection covers. To include the system and system configuration and all associated signing in and signing out procedure
- K2 the principles and practice of returning the system to service including the resetting parameters
- K3 the range of your responsibilities and how to discharge those responsibilities
- K4 how to access and communicate with the personnel relevant to task completion
- K5 the relevant documentation to complete
- K6 how to identify, record and highlight potential mis-measurements
- K7 the personnel relevant to preparing for worksite departure
- K8 client requirements for data presentation
- K9 your responsibilities regarding the close-out meeting

COGMP4

Perform post-measurement processes operations

Additional Information

Scope/range related to knowledge and understanding

You will be expected to demonstrate your competence in performing post- job operations in the maintenance or proving context.

- 1 how to select, use and care for Personal Protective Equipment (PPE) including sight/hearing protection, gloves, footwear, hard hats, appropriate work wear
- 2 the implications of statutory and organisational requirements
- 3 how to interpret operational requirements, to include policies, procedures, instructions, codes of practice, standards and schedules
- 4 appropriate International standards
- 5 how to work with and within the Permit to Work system
- 6 specialist safety and technical knowledge

COGMP4

Perform post-measurement processes operations

Developed by Cogent

Version number 1

Date approved May 2010

Indicative review date May 2012

Validity Current

Status Original

Originating organisation Cogent

Original URN MP4

Relevant occupations Engineering and manufacturing technologies; Manufacturing technologies; Process, Plant and Machine Operatives; Plant and Machine Operatives

Suite Measurement Processes

Key words perform, post-measurement, processes, worksite, inspection, departure
